

Bulletin No.: 13 003 80(2021)

Motorcycles lacking this modification may experience a mid-range flat-spot in the carburetion as the restricted air intake creates an overly rich condition in the combustion chamber.

Dealers performing this modification will be reimbursed 6 AW on submission of a completed warranty request form.

BMW MOTORRAD GMBH
After-Sales Service
Munich